

SECRET

OUT 56697

SECRET 151809Z

1035 SEP 15 18 25Z

25X1

1. CAMERA B 23 WAS USED IN MISSION 8042 FLOWN ON 12 SEPTEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:


A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. 9R SIDE: BOTH FILM EDGES CONTAIN SMALL STATIC DISCHARGE TRACES. CAMERA ROLLER-INDUCED DISCHARGE TRACES ARE PRESENT ON BOTH FORMAT EDGES. A FEW PLUS DENSITY STREAKS APPEAR INTERMITTENTLY ON THE INBOARD EDGE OF THE FILM. BREAKDOWN SPLICES ARE POSITIONED BETWEEN FRAMES 099/100, 1333/1334, 1495/1496 AND 2364/2365. ANOTHER BREAK-DOWN SPLICE IS PRESENT WITHIN THE FORMAT OF FRAME 1326 AND A MANUFACTURER'S SPLICE IS INSIDE FRAME 1335.

C. 9L SIDE: BOTH EDGES CONTAIN SMALL STATIC DISCHARGE TRACES. CAMERA ROLLER-INDUCED DISCHARGE TRACES ARE PRESENT ON THE INBOARD EDGE. FRAMES 0002, 0232, 2642, 2646 AND 2648 CONTAIN TRANSVERSE LIGHT LEAK TRACES. A FEW PLUS DENSITY AND MINUS DENSITY STREAKS APPEAR AT RANDOM THROUGHOUT THE FILM. FRAMES 001 TO 056 CONTAIN A ROW OF MINUS DENSITY DOTS SPACED 1.55" APART AND RUNNING PARALLEL TO AND 2.0" FROM THE INBOARD EDGE OF

15 SEP 1965

COPIES RECEIVED		
Cy No.	Office	Act
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3, 4	TID	✓
	PID	
	PAG	
	DIAX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

SECRET

Declassification Review by NGA/DoD

-2-

THE FILM. A BREAKDOWN SPLICE IS INSIDE FRAME 1296 AND OTHER SPLICES ARE POSITIONED BETWEEN FRAMES 0725/0726, 0734/0735, 1331/1332, 2461/2462, AND 2548/2549.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0001 TO 2648.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FAULTS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD IN HAZE-FREE AREAS.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURED 35 PERCENT OF THE TERRAIN COVERED

IN THIS MISSION.

S E C R E T

-END OF MESSAGE-